# <u>Rice Lake TC</u>

Tuning Fork Compact Electronic Balance

# **Operation Manual**



### **IMPORTANT**

- To ensure safe and proper use of the balance, please read this manual carefully.
- After reading this manual, store it in a safe place near the balance, so you can review it as needed.



### PREFACE

Thank you for purchasing an RL-TC Series electronic balance. This is a precision instrument equipped with exacting mechanisms in a compact body. The RL-TC series provides enhanced functions, including a counting mode for stock control of parts, a percentage mode for comparative measurements given in percentages, and a limit function for measuring constant quantities by consecutive weighings. Despite its many functions, the balance is easy to operate and features user-friendly keys. Furthermore, the large liquid-crystal display provides excellent visibility, and the instrument's high speed and stability–intrinsic to a tuning fork design–help boost operational efficiency.

Before using the balance, please check that the following items have been included in the package. Should you find any missing parts, please contact your local dealer or our marketing division at once.

(1) Main unit of balance



(2) Measurement pan (one round or square pan)

Round pan • RL-TC -220~620: φ



Square pan • RL-TC -1200:170mm× 140mm • RL-TC -2200~12K:180mm × 160mm

(3) Pan base (4)
 (one small for the round-pan balance; one large for the square-pan balance)
 for Round pan for Round pan for Square pan

(4) AC adapter

## **CONTENTS**

PF	EFAC	ЭЕi				
СС	NTE	NTSi				
1.	Precautions on the Use1					
2.	Nam	es of Component Parts4				
	2.1	Main Unit 4				
	2.2	LCD Indicators and Operating Keys5				
	2.	2.1 Symbols Displayed5				
	2.	2.2 Names and Functions of Operating Keys6				
3.	Basi	c Operations7				
	3.1	Installation7				
	3.2	Operation Check8				
	3.3	Operation for Tare Subtraction9				
4.	Func	tions11				
	4.1	Setup and Checking of Functions 11				
	4.2	Description of Functions12				
	4.3	Interface Section 13				
5.		ching Function for Units of Measurement				
		Switching Units of Measurement 14				
		Setup of Units of Measurement 14				
6.		nting Pieces16				
0.		Sampling 16				
		Increasing the Counting Accuracy (Memory				
	0.2	Update Method) 18				
7.	Meas	suring Percentage20				
8.	Limit	Function22				
	8.1	Limit Function Setup 22				
	8.2	Setup of Limit Values by Actual Quantity Loads				
	0.0					
	ð.3	Setting up Limit Values by Inputting Values				

9. Calibrating the Balance ......27

	10. Operating the Balance with the	
	10.1 Specifications	.29
	10.2 Charging Method	.29
	10.3 User Precautions	.29
11.	Troubleshooting	.30
12.	Specifications	.31
	12.1 Basic Specifications	.31
	12.2 Common Specifications	.31
	12.3 Minimum Display by Unit of Mea	
13.	Conversion Table of Units	.34
TC	Series Limited Warranty	.35

### 1. Precautions on the Use

- This Section "Precautions Relating to Use" sets forth precautionary notes that the user should observe in order to prevent physical injury to the user and/or damage to property.
- The nature of problems that may result in the event of improper operation, and consequential effects on the quality and performance of the balance, are indicated under the two categories of "Caution" and "Recommended," and explained using symbols.



This symbol indicates a risk of injury or property damage if the balance is used improperly. Be sure to observe these notes to ensure safe use o-f the balance as the improper use may cause serious results.

RECOMMENDED

This term indicates steps that the user should take to ensure the quality and reliability of the balance.



Meanings of Symbols Each symbol is accompanied by an instruction. Indicates a "mandatory" action that should be executed without fail.






Indicates a "prohibited" action that must not be executed.






Do Not Disassemble	<ul> <li>Do not disassemble or modify the unit.</li> <li>Could cause malfunction or heat generation</li> <li>Contact our Marketing Division or Technical Service Division.</li> </ul>
Do Not Deviate from Ratings	<ul> <li>Only AC power (rated value) should be used.</li> <li>Only use the dedicated AC adapter.</li> <li>Use of other types of power or adapters may result in heat generation or malfunction of the balance.</li> </ul>
Do Not Move	<ul> <li>Do not move the balance when a sample is loaded.</li> <li>The loaded sample may fall off the measurement pan and cause an injury.</li> </ul>









- Calibrate the balance after installation or relocation.
  - Measurement values may contain errors, preventing accurate measurement from being conducted.








## 2. Names of Component Parts

#### 2.1 Main Unit


Round-pan types (TC-220, TC-420, TC-620) Square-pan types (TC-1200, TC-2200, TC-4200, TC-6200, TC-12K)



To be the best by every measure\*

### 2.2 LCD Indicators and Operating Keys

#### 2.2.1 Symbols Displayed



Display	Description						
g	Grams						
→0←	Zero point						
→T←	Tare being subtracted						
0	Indication of stable balance (If the light is off, the balance is unstable.)						
*	Balance powered up (Lights up when the power is turned off) or data transmitted						
Pcs	Counting mode						
%	Percentage mode						
<ul><li></li></ul>	Indication of judgement result (HI/OK/LO) when the limit function is active.						
mom	Momme						
М	Display of set values from memory (If a value is flashing, it is being saved.)						
CAL	Stays on and flashes while span adjustment is in progress.						
<b>Ounhunhun F</b> Bar graph							
	[ ct) carat						
	[ OZ ] (oz) ounce						
	[ <b>]</b> [lb) pound						
出版で	[oz t] (ozt) troy ounce						
	[dレッセ] (dwt) penny weight						
	[ (Upper right) ] grain						
	[+] (tl) tael (Hong Kong)						
	[+] Upper right ] (tl Upper right) tael (Singapore, Malaysia)						
	[ <b>ナ</b> ト <sub>Lower</sub> right ] (tl ト <sub>Lower</sub> right) tael (Taiwan)						
	[to) tola						
	Lights up when the balance is battery-operated. The indication changes to [1] ] when the battery capacity decreases and charging is required. (See "10. Operating the Balance on the Battery" on page 29.)						




#### 2.2.2 Names and Functions of Operating Keys

Operating Key			Function	
On/Off	On/off key	Key to turn on/off the unit power		
( Memory	Memory key	[Brief press] [Brief press]	initiates print or output. saves the settings of the number of pieces or percentages (%), or the limit value when	
Target	Target key	[Brief press] [Continuous press]	using the limit function. starts setting the number of pieces or percentages (%). starts setting the limit value when using the	
		[Brief press]	limit function. toggle-switches the units to be displayed in succession (g, Pcs, %, etc.).	
F	Function key	[Brief press] [Brief press] [Continuous press]	moves the flashing digit in the setup of a limit value when using the value input method. selects an item when setting the function. invokes various functions.	
→0/T← Zero/Tare	Zero/Tare key	[Longer continuous press] [Brief press] [Brief press] [Brief press]	invokes span adjustment. resets the indication to zero when using zero-point setup or tare subtraction. selects a value with the value input method when using the limit function. selects a function when operating the balance in the function mode.	




### 3.1 Installation






### 3.2 Operation Check






### 3.3 Operation for Tare Subtraction



 $\bigstar$  Weighing only the weight of an added sample







### $\bigstar$ Key Points of the Procedure $\bigstar$

The following applies equally to all the measurement modes for weight measurement, counting, and percentages.


- 1. After the balance is switched off, there is still enough current to display [\*]. This indicates that the AC adapter is connected to an electrical outlet, but that the balance is turned off. ゼロ点 ひょう When the balance is switched on again, [\*] will disappear. ※If the balance is running on batteries and the unit is switched off, the display does not display **Dhilling**
- The bar graph shows the current load status with respect to the capacity of the balance. The nearer the [F] mark draws, the smaller the measurable weight becomes.
   ※Even when the display currently indicates zero with the tare subtracted, the weight corresponding to the subtracted tare is indicated on the bar.



3. When the balance remains stable, the stability indicator [O] remains on. If the balance becomes unstable, the stability indicator [O] will disappear. When a displayed value flickers or the stability mark flashes on and off, it is likely that the balance is being affected by wind or other vibrations. Use the windshield or vibration dampers to protect against such adverse effects.



When the read-out indicator is reset to zero or the tare is subtracted, the balance indicates zero this way: [→ 0 ←].
 If the tare is subtracted, the indicator reads as follows: [→ T ←].



- 5. When the tare is subtracted, the measurable range is reduced. Measurable Range = Capacity - Tare Weight
- 6. If  $[\square E \neg \neg]$  appears when a sample is loaded, the measurable range has been exceeded.
- 7. In counting mode or percentage mode, if no sample is stored in memory the indicator will not change, even when the measurement pan is pressed.
- 8. The measurement mode that is activated when the balance is switched on will be the one that was active when last switched off. For example, if the balance was switched off in counting mode, this counting mode will be reactivated the next time the balance is switched on.



### 4.1 Setup and Checking of Functions

	Invoking the function	Press and hold down the Function key until the indicator changes to " $F unc$ ," then release the key. The function setup mode is activated, and the first item, [1.b.5.1 (Bar graph) 1] appears. (See "4.2 Description of Functions" on page 13.)
2	Selecting the next item	Press the Function key. The indication changes to the next item, 2 5 E L 0 [(Limit function)].
3	Selecting an item	Pressing the Function key advances the function items at the rate of one item per press.
4	Changing the content of an item          71. DL. 7       71. DL. 7         Image: Content of an item       Image: Content of an item	Select the item to be changed with the Function key. Each press of the Zero/Tare key changes the digit on the right end. Select the desired one.
5	71. DL. 1     DDD g	Press the Target key. The balance terminates the function setup and returns to measurement mode.



### 4.2 Description of Functions

Item		Set Value		Descripti	on		
_		Π		Disable			
Bar graph display		1. Б.Б.	☆1	Enable			
			☆0	Disable	Disable		
Limit function		2.5EL	1	Enable	Enable		
<b>.</b>	Judgement	<b>.</b>	☆1		Always judge (judges even when the balance is unstable)		
in limit ted	condition	21.E o.	2		Judge only when the balance is stable (does not judge if the balance is unstable)		
Displayed only when limit function is activated	Judgement range	22.L	۵		Ranges beyond +5 graduation is judged (ranges +5 graduation or below, including negative ranges, are not judged.)		
ayed o	Tange		☆1	the negation	tive, is judged).	e entire range, including	
spla	Number of	23.P	1	One-poin	t setup (judges betw	een OK and LO)	
Ō	points for judgement		☆2		nit and lower-limit val I, OK and LO).	ues are set up (judges	
Au	ito-zero	3.R.O	Ω	Disable		atically sets the zero point	
(zero	o-tracking)		☆1	Enable	exactly to zero to pre	event slight deviations.	
Auto	power-off	4.R.P.	۵	continuo		This function is available only when the balance is	
7010	power-on	¬.п.г.	☆1		palance powers off in ately three minutes)	battery-operated.	
			0	Measure	ment by consecutive	weighings.	
			1				
Respo	onse speed	S.rE.	2	Fast			
			☆∃	↓ ↓			
			4	Slow			
			5				
			i 	Wide (mi	ld)		
Stability	/ parameters	6.S.d.	\$2 ∽	↓ ↓			
			<u> </u>	Narrow (strict)			
				Disable i	nput/output		
In	terface	Л. 1.F.			numeric format		
Interface			ר ( ה	Seven-digit numeric format			
			☆1 □1	[g]	<u> </u>		
Setup of units of			☆2 14	[ <b>[ [ [ [ [</b> ]] (ct			
measurement to be		8 (5.4	15	[ <b>0Z</b> ](0)	,		
displayed		5	15	[ <b>b</b> ](b			
	er selected	85.S.u.					
measuring units with			18	102 C			
Fund	ction key.		*19		er right ] (grain)		
			10		5 1 (5 - 7		

Items marked  $\Rightarrow$  are the default factory settings.  $\Rightarrow 1 \sim \Rightarrow 5$ : default settings  $[B_{1.5} ...] \sim [B_{5.5} ...]$ 

\*Not available in TC-12K.



#### 4.2 Description of Functions (cont.)

Setup of	8 (5.u. S	18	[ 🛨 ] (tl_Hong Kong)
measurement units			[ ᡶᠯ ▶ Upper right] (tl_Singapore,Malaysia)
to be displayed <sup>**1</sup>		1[	[ ᡶ╏ ► Lower right] (tl_Taiwan)
		12	[mom]
Register		15	[ <b>to</b> ](to)
measurement units		☆3 /⊇ /]	[Pcs]
by selecting Function key		☆4 <i>1F</i>	[%]
		☆5 🛛 🖓	Unit not set

\* 1  $[\square \square]$  cannot be set at  $[\square \square]$ .

### 4.3 Interface Section

Displayed when  $[\mathcal{T} \ \mathcal{LF} ]$  is set to  $[\mathcal{L}]$  or  $[\mathcal{L}]$ 

Item	Set Value		Description		
		Ω	Stop output		
		1	Output continuous	s at all times	
		2	Output continuous	s if stable (stop output if unstable)	
		3	Outputs once by p whether stable).	pressing <u>Memory</u> key (irrespective of	
		ч	when a sample is	able. Outputs if the balance is stable loaded after the preceding sample has d the balance indicated zero, or less.	
Output Control	7 ( a.c.	5	Outputs once if stable, and stops output when unstable. Even if the sample is not replaced, the balance is output once when it stabilizes next time (including the zero indication).		
			5	unstable. Even if	able, and outputs continuously when the sample is not replaced, output of when it stabilizes after being output
		\$7	Pressing <u>Memory</u> key causes the balance to output once when stable.		
Baud Rate	72. b.L.	+ 1 2	1200 bps 2400 bps		
Dada Halo	1	3	4800 bps		
		Ч	9600 bps		
Parity	TEPR	☆ <i>□</i> /	044	Displayed only when [7, 1/F, 2]	
-		2	Even	(7-digit numeric format)] is specified.	

☆ denotes a factory-setting


X The data interval in continuous output mode is 0.1 to 1 second. (The interval varies depending on weighting conditions and other factors.)



## 5. Switching Function for Units of Measurement

Pressing the Function key allows the user to switch the unit of measurement to [g], [ct], [%], and so on. During setup, a maximum of five different units can be registered for use in function setup mode.


#### 5.1 Switching Units of Measurement




#### 5.2 Setup of Units of Measurement

When values [B1.5.u.] to [B5.5.u.] are entered prior to use, the desired unit of measurement to be displayed can be chosen simply by pressing the Function key. For more information on the units of measurement that can be set here, please refer to "4.2 Description of Functions" on page 13.

Example: To change the default factory settings to pound units, use [82.5....] in the factory settings.







### $\bigstar$ Key Points of the Procedure $\ddag$


- When set values are entered in the function items [8 1.5...] to [8 5.5...] prior to use, the desired unit of measurement to be displayed can be selected simply pressing the Function key. For more information on the units of measurement that can be set, please refer to "4.2 Description of Functions," on page 13.
- 2. The units are displayed in the same sequence as the settings made from [8 1 5 ...] to [8 5 5 ...].
- 3. If [[] [] is set, no unit of measurement will be displayed, even when units of measurement are set in subsequent items.
- 4.  $[\square \square]$  cannot be set in  $[\square I \subseteq \square]$ .
- If the same unit of measurement is set multiple times, the second time (and all subsequent times) the unit(s) occurs, it will be ignored when the display switches.



# 6. Counting Pieces


To implement piece-counting, the specified samples are loaded on the balance, and their average unit weight (hereinafter, simply the "unit weight") is entered and saved. The procedure for saving unit weights is called sampling.

The counting procedure consists of loading articles that have already been sampled on to the balance. The number of pieces is then calculated by dividing the total weight of the loaded articles by the unit weight saved in memory. Piece counting cannot be implemented unless sampling has already taken place.



%If samples to be counted deviate widely in weight, or a higher measure of accuracy is desired, it is recommended that users use the "Raising the Counting Accuracy" method. This procedure results in greater precision by increasing the number of samples used in the sampling operation.

### 6.1 Sampling





4 Changing the sampling n	umber. if necessarv.	If samples to be counted widely deviate
PCS PCS PCS PCS PCS PCS PCS PCS	How to change the value 10  10  10 100  30 100  50  10	in weight, or a higher measure of accuracy is desired, it is recommended that users change the sampling number to a larger value. Press the Zero/Tare key. Each press of the key changes the value on the right end. Select the desired value. If the sampling number need not be changed, go on to the next step.
5 Loading samples	PCS     011   30     \ 	Load the number of samples displayed. Count the samples precisely and load them in the center of the measurement pan.
6 Saving the unit weight of	samples	Press the Memory key.
	Pcs 30 000 + F 00P Note 2000	The balance saves the unit weight and reverts to measurement mode.



### $\bigstar$ Key Points of the Procedure $\bigstar$

- While the samples are being saved, the value indication disappears and only [M] flashes to indicate that memory saving is underway. If the balance is affected by wind or other vibrations during this process, the saving time may be prolonged.
- 2. If [/\_ / / ] appears, it indicates one of the following states:
  - The weight of one sample (measurable unit weight) is insufficient. For the range of unit weights that can be measured and saved, please refer to "12. Specifications," on page 31.
  - (2) In the sampling of Operation Step 3, press the Set key with the samples loaded on the balance.

※ If [/\_ - 左 ,- ,- ] appears, the sampling is interrupted and the data in progress is not saved.


The operation for increasing counting accuracy is referred to as the Memory Update Method. This
procedure updates the memory with a unit weight that represents a more precise average by
gradually increasing the sampling number.
 This operation improves counting accuracy and is recommended for the following cases:

This operation improves counting accuracy and is recommended for the following cases;


- (1) When the samples to be counted deviate widely in weight or the number of samples displayed deviates.
- (2) When greater accuracy is desired.
- If [A d d] appears in Memory Update Method, it indicates that a counting error is likely due to the small number of the samples loaded on the balance. [◄] will light up at the judgment indication "LO." As the memory update continues, counting accuracy improves and the above indication disappears.
- 5. If you change the sampling number, subsequent sampling will start from the new sampling number.

### 6.2 Increasing the Counting Accuracy (Memory Update Method)

\*This procedure is the same as the sampling procedure described on the previous page up, to the point at which the sampling number is changed.









### 7. Measuring Percentage

The percentage measurement function operates by weighing an actual sample, selected as the reference, and saving its weight as the reference value and indexing it as 100%. When a measurement sample loaded on the balance is lighter or heavier than the reference, its weight is indicated as a percentage (%) value relative to the reference weight.

1 Activating the percentage mode	Press the Function key to disaplay [%].
2 Setting the reference value	Press the Target key.
P. SET %	The display begins flashing $[P \ \subseteq E \ L]$ . The balance is now ready for reference value setup.
3 Loading the sample	Load the reference sample.
4 Saving the reference value	Press the Memory key.
	The balance indexes the weight value of the reference sample as 100% and returns you to measurement mode.
5 Loading a sample to be measured	The balance now indicates the weight of
B5.37 %	the loaded sample as a percentage (%) value relative to the reference value.



### $\bigstar$ Key Points of the Procedure $\bigstar$

- 1. While samples are being saved, the value indication disappears temporarily, and only the [M] mark flashes. If the balance is affected by wind or other vibrations during this process, the saving time may be prolonged.
- 2. If [/\_ E -] appears briefly, it indicates one of the following states:
  - (1) The weight of the reference sample is insufficient. For the limit weight that can be saved (% limit weight), please refer to "12. Specifications," on page 31.
  - (2) While setting up the reference value in Step 2, the Set key has been pressed while the samples were loaded on the balance.
  - %If [L E r] appears, sampling has been interrupted and the sample value being processed will not be saved.
- 3. The minimum intervals between percentages in the unit switch from 1%, to 0.1%, to 0.01%, depending on the reference weight from the sampling.



# 8. Limit Function

The limit function judges measurements according to a limit value saved in the balance.

The function shows the judgement result by displaying the [◀] mark as either HI (excessive), OK (appropriate), or LO (insufficient). This function is very useful when discriminating between conforming and nonconforming articles. It is also useful when measuring a given constant quantity consecutively, in conjunction with a range of reference weights defined by upper- and lower-limit values.

This function can be used in weight mode, counting mode, or percentage mode.

Limit value input methods

Either of the following two methods can be used in the different modes:

- (1) Actual quantity setup method....... An actual sample is loaded on the balance and its weight saved as the limit value.
- (2) Numeric value setup method ....... The limit value is entered with a key stroke.

%The limit values entered are held in memory, even when the balance is powered down.


%The respective limit values for weight mode, counting mode, and percentage mode are set up independently.

#### Indication of judgment result

The [◀] mark lights up as either HI, OK, or LO on the left side of the display, indicating the result of judgement.


Judgement Results	Upper/lower-limit setting	One-point setting
HI (excessive)	Upper-limit value < measurement value	No indication
OK (appropriate)	Upper-limit value ≥ measurement value ≥ lower-limit value	Limit value ≤ measurement value
LO (insufficient)	Lower-limit value > Measurement value	Limit value > Measurement value

### 8.1 Limit Function Setup






### 8.1 Limit Function Setup (cont.)





### 8.2 Setup of Limit Values by Actual Quantity Loads






### 8.3 Setting up Limit Values by Inputting Values

1	Starting the limit function		Press and hold down the Target key.
		L. SET	Release the key when [L. 5EL] is displayed. The currently set lower-limit value flashes.
	ontinuous pressing	Key released	
2	Opening the value input scree	en	Press the Zero/Tare key.
			All the digits are displayed, with the one on the right end flashing. This flashing digit is the one that can be changed.
3	Entering a value		Press the Zero/Tare key again. Pressing the key repeatedly changes the flashing value until the desired number is entered.
4	Selecting a digit		Press the Function key. The flashing moves to the digit on the immediate left. Each time the key is pressed, the flashing digit moves one position left. When the leftmost digit is selected, the flashing advances to the rightmost digit position.
5	Repeat Steps 3 and 4		Enter the lower-limit value by selecting a value with the Zero/Tare key and moving the digits with the Function key, as needed.
6	Saving the lower-limit value	→ 1 77.35 g	Press the Memory key. After saving the lower-limit value, the balance displays it briefly and proceeds to the next setup. XIf one-point setup was chosen, the setup is complete.
7	Setting up the upper-limit valu	Je	The display changes to $[H \cdot 5EL]$ , indicating that the upper-limit value can be set. If there is an upper-limit value already set, that value will flash.




### 8.3 Setting up Limit Values by Inputting Values (cont.)



### $\bigstar$ Key Points of the Procedure $\bigstar$

1. The limit values you have set can be checked each time you press the <u>Set</u> key. The balance displays the lower-limit value after showing [ *L*. *SET* ], and the upper-limit value after showing [ *H. SET* ].



- 2. If you make a mistake, press the Function key during the setup of actual quantities or the Set key during the setup of values.
- 3. If you press the <u>Memory</u> key while a value is flashing, an actual quantity will be set based on the weight currently loaded on the balance. Pressing the <u>Zero/Tare</u> key at this time displays the value input screen.
- 4. If the [◀] mark lights up for all three judgement indicators, HI, OK, and LO, the lower-limit value set exceeds the upper-limit value. Check the values, since mistakes can occur with entries, as in cases when the upper-limit value is specified with a negative sign.
- 5. When the [M] mark is flashing on the value input screen, the sign on the left end can be changed. Press the Zero/Tare key to switch between the positive and negative signs.




## 9. Calibrating the Balance

Since electronic balances are affected by gravity gravitational acceleration, they produce different values in various locations. Therefore, before use, balances must be calibrated at the location where they are installed. Calibration is also required after long periods without use, or if a balance begins to produce inaccurate values.


Calibration of a balance, or "span adjustment," is required to produce accurate measurements.

X Span adjustment should be performed with the balance installed perfectly level and without any load on the measurement pan.





### Calibrating the Balance (cont.)



### $\bigstar$ Key Points of the Procedure $\bigstar$

- 1. Pressing the Function key in Step 2 interrupts the span adjustment and returns you to the original measurement mode.
- 2. The calibration weight used for span adjustment should be heavier than half the capacity of the balance.

To implement a calibration as precisely as possible, use a weight close to the capacity of the balance.

- % Calibration weights can be ordered from Shinko. For ordering information, please contact Shinko.
- 3. If problems arise during span adjustments, one or more of the following error messages will appear:
  - (1) [ E - ]: The calibration weight exceeds the capacity of the balance.
  - (2) [ / E - ]: The calibration weight is less than half the capacity of the balance.
  - (3) [, - - ]: The difference between before and after calibration values is too large (1.0% or more).

% If error messages are displayed, calibration cannot take place.

Check the weight and re-calibrate. If the same error continues after repeated calibrations using the correct weight, please contact our Marketing Division or Technical Service Division.



### 10. Operating the Balance with the Battery

This function can be used only when the balance is battery-operated.

#### 10.1 Specifications

- Built-in nickel-metal hydride battery
- Charging time: Approximately 12 hours
- Drive time: Approximately 32 continuous hours
- Number of charge/discharge cycles:300 or more

#### 10.2 Charging Method

While the balance is battery-operated, [1] stays on. The indicator flashes [1] (charging required) when battery capacity decreases. If the balance flashes [1], charge the battery by following these steps:

- (1) Connect the dedicated AC adapter to the balance.
- (2) Turn the balance off.
- (3) Charging takes approximately 12 hours, with power switched off. Charging the battery longer than 12 hours decreases battery life.

#### **10.3 User Precautions**

- 1. Once charging is complete, use the balance without the AC adapter to avoid over-charging. This can occur since the balance continues to charge the battery with a weak current when the power is switched on. <u>Overcharging will also decrease battery life</u>.
- When the balance is used for the first time after purchase, the operating time may be shorter than when using a fully charged battery. This is due to natural discharge of the battery. Although the balance can be used while [1] is flashing, it should be recharged as soon as possible.
- 3. When the battery displays no indication, or an indication disappears quickly after the balance is switched on, battery capacity is low. In these cases, either charge the battery immediately or plug in the AC adapter.
- 4. Charging the battery while [1] is displayed reduces battery life.

**Cautions** To operate the balance safely, observe the following (failure to do so could result in malfunctions, breakage, burst batteries, or fire):

- 1. Do not disassemble or modify the battery. Do not reverse the balance connection or short-circuit the positive and negative polarities of the balance.
- 2. Use only the supplied AC adaptor.
- 3. Do not incinerate used batteries. Dispose as hazardous material only.



Symptom	Cause	Possible remediation
	The AC adapter is not connected.	$\rightarrow$ Check that the AC adapter is connected (8).
The display is unstable. [M] remains flashing without changing.	<ul> <li>The balance is subject to air currents or vibration.</li> <li>The balance is situated on an unstable surface.</li> <li>An object is contacting the sample being measured, the measuring pan, or the tare.</li> </ul>	→ Check Precautions on Use (2–4).
Weight indication contains an error.	<ul> <li>An error was made in the tare subtraction procedure.</li> <li>The adjusters remain lifted, resulting in an incorrect level.</li> <li>The indication values are inconsistent after long hours of use, or because the balance has been moved to a new location.</li> </ul>	<ul> <li>→ Review the tare subtraction (10).</li> <li>→ Check the level (8).</li> <li>→ Execute span adjustment on the balance (27).</li> </ul>
The limit function does not work.	<ul> <li>The limit function is not selected.</li> <li>The limit value has been erroneously entered.</li> </ul>	→ Check the operation of the limit function (22 on).
[月台台] appears ([◀ ] and a value flash at [LO].)	<ul> <li>Likely to produce errors in the counting mode because the sample weight is insufficient.</li> </ul>	→ Execute the Memory Update Method (19).
$[\Box - E \neg r]$ appears before the capacity is reached.	<ul> <li>Gross weight exceeded the capacity of the balance (weight range = container + weight of sample).</li> <li>A section of the mechanism is damaged.</li> </ul>	<ul> <li>→ Check the total weight.</li> <li>→ Execute tare subtraction again.</li> <li>→ Contact our Technical Service Division or your local dealer.</li> </ul>
[u - Err] is displayed.	<ul> <li>A foreign object is caught between the measuring pan (pan base) and the balance.</li> <li>A section of the mechanism is damaged.</li> </ul>	→ Remove the measurement pan and examine the surface beneath it.
[占 - Err] is displayed. [d - Err] is displayed.	<ul> <li>The balance is exposed to static electricity or noise.</li> <li>The electrical system of the balance is malfunctioning.</li> </ul>	→ Contact our Technical Service Division or your local dealer.
During span adjustment [	<ul> <li>A weight heavier than the capacity was used.</li> <li>The reference weight is less than 50% of the capacity.</li> <li>Calibration produced an error of 1.0% or more.</li> </ul>	→ Check that the span adjustment procedure was performed correctly (27).
During battery installation: The indication disappears. [I_] flashes. No indication is produced.	<ul> <li>The automatic power-off function was activated.</li> <li>The battery capacity is low.</li> </ul>	<ul> <li>→ Switch on the power again. Deactivate the Automatic power-off function, if necessary (13).</li> <li>→ Recharge the battery (29).</li> <li>→ Operate the balance with the AC adapter.</li> </ul>

X The numbers in ( ) indicate reference pages



### **12.1 Basic Specifications**

Model	TC-220	TC-420	TC-620	TC-1200
Capacity [g]	220	420	620	1200
Readability [g]	0.01	0.01	0.01	0.1
Measurable unit weight in counting mode [g]	0.01	0.01	0.01	0.1
Minimum weight in percentage mode [g]	1	1	1	10
Weight measuring method	Tuning fork vibration method			
Calibration method	With external calibration weight			
Pan Size [mm]	φ140 170x140			170x140

Model	TC-2200	TC-4200	TC-6200	TC-12K
Capacity [g]	2200	4200	6200	12000
Readability [g]	0.1	0.1	0.1	1
Measurable unit weight in counting mode [g]	0.1	0.1	0.1	1
Minimum weight in percentage mode [g]	10	10	10	100
Weight measuring method	Tuning fork vibration method			
Calibration method	With external calibration weight			
Pan Size [mm]	180 x 160			

### **12.2 Common Specifications**

(1) Tare subtraction range...... Total capacity

(2)	Liquid-crystal display (LCD)	Seven segments (two segments in leading part Maximum digits indication: seven digits, Segment height: 16.5 mm.	),
(3)	Measuring function	Weight mode, counting mode, and percentage mo	ode
(4)	Overload indication	[ $\Box$ - $E \land r$ ] is displayed if weight capacity + 9 inter-	rvals are exceeded.
(5)	Compatible printer	CSP-160	
(6)	Operating temperature and humidity ranges	5°C to 35°C, 80%RH or less	
(7)	AC adapter	Dedicated AC adapter: 120V AC - 9V DC, or	230V AC - 9V DC
(8)	Options	RS232C Output	
		Rechargeable battery operation	



Model Unit_of measurement	TC-220	TC-420	TC-620	TC-1200
	220	420	620	1200
g	0.01	0.01	0.01	0.1
ርቲ (ct)	1100	2100	3100	6000
	0.05	0.05	0.05	0.5
	7.7	14	21	42
<b>DZ</b> (oz)	0.0005	0.0005	0.0005	0.005
<b>Њ</b> (Ib)	0.48	0.92	1.3	2.6
	0.00005	0.00005	0.00005	0.0005
مع خ (ozt)	7	13	19	38
	0.0005	0.0005	0.0005	0.005
dייב (dwt)	140	270	390	770
	0.01	0.01	0.01	0.1
► (grain)	3300	6400	9500	18000
(grain)	0.2	0.2	0.2	2
さ	5.8	11	16	32
(Hong Kong)	0.0005	0.0005	0.0005	0.005
せ	5.8	11	16	31
(Singapore, Malaysia)	0.0005	0.0005	0.0005	0.005
<b>र्ट।</b> (Taiwan)	5.8	11	16	32
(iaiwaii)	0.0005	0.0005	0.0005	0.005
mom	58	110	160	320
(momme)	0.005	0.005	0.005	0.05
<b>to</b> (to)	18	36	53	100
	0.001	0.001	0.001	0.01

### 12.3 Minimum Display by Unit of Measurement

The view of the table

Upper cell :	Capacity
Lower cell :	Readability



### Minimum Display by Unit of Measurement (continued)

Model Unit of	RL-TC- 2200	RL-TC- 4200	RL-TC- 6200	RL-TC- 12K
measurement	2200	4200	0200	1211
g	2200	4200	6200	12000
9	0.1	0.1	0.1	1
ርቲ (ct)	11000	21000	31000	60000
	0.5	0.5	0.5	5
<b>OZ</b> (oz)	77	140	210	420
	0.005	0.005	0.005	0.05
<b>/b</b> (lb)	4.8	9.2	13	26
	0.0005	0.0005	0.0005	0.005
oz ቲ (ozt)	70	130	190	380
	0.005	0.005	0.005	0.05
dייד (dwt)	1400	2700	3900	7700
	0.1	0.1	0.1	1
▶ (grain)	33000	64000	95000	
(grain)	2	2	2	
<i>t</i> /	58	110	160	320
(Hong Kong)	0.005	0.005	0.005	0.05
t!	58	110	160	310
(Singapore, Malaysia)	0.005	0.005	0.005	0.05
t। (Taiwan)	58	110	160	320
Li (Taiwan)	0.005	0.005	0.005	0.05
mom	580	1100	1600	3200
(momme)	0.05	0.05	0.05	0.5
	180	360	530	1000
<b>to</b> (to)	0.01	0.01	0.01	0.1

The view of the table

Upper cell : Capacity Lower cell : Readability



### **13. Conversion Table of Units**

Unit	Gram	carat	Ounce	Pound	troy ounce	Penny Weight
1g	1	5	0.03527	0.00220	0.03215	0.64301
1ct	0.2	1	0.00705	0.00044	0.00643	0.12860
1oz	28.34952	141.74762	1	0.06250	0.91146	18.22917
1lb	453.59237	2267.96185	16	1	14.58333	291.66667
1ozt	31.10348	155.51738	1.09714	0.06857	1	20
1dwt	1.55517	7.77587	0.05486	0.00343	0.05	1
1GN	0.06480	0.32399	0.00229	0.00014	0.00208	0.04167
1tl (HK)	37.429	187.145	1.32027	0.08252	1.20337	24.06741
1tl (SGP,Mal)	37.79936	188.99682	1.33333	0.08333	1.21528	24.30556
1tl (Taiwan)	37.5	187.5	1.32277	0.08267	1.20565	24.11306
1mom	3.75	18.75	0.13228	0.00827	0.12057	2.41131
1to	11.66380	58.31902	0.41143	0.02571	0.37500	7.5

unit	Grain	tael (Hong Kong)	tael (Singapore, Malaysia)	tael (Taiwan)	momme	Tola
1g	15.43236	0.02672	0.02646	0.02667	0.26667	0.08574
1ct	3.08647	0.00534	0.00529	0.00533	0.05333	0.01715
1oz	437.5	0.75742	0.75	0.75599	7.55987	2.43056
1lb	7000	12.11874	12	12.09580	120.95797	38.88889
1ozt	480	0.83100	0.82286	0.82943	8.29426	2.66667
1dwt	24	0.04155	0.04114	0.04147	0.41471	0.13333
1GN	1	0.00173	0.00171	0.00173	0.01728	0.00556
1tl (HK)	577.61774	1	0.99020	0.99811	9.98107	3.20899
1tl (SGP,Mal)	583.33333	1.00990	1	1.00798	10.07983	3.24074
1tl (Taiwan)	578.71344	1.00190	0.99208	1	10	3.21507
1mom	57.87134	0.10019	0.09921	0.1	1	0.32151
1to	180	0.31162	0.30857	0.31103	3.11035	1



### **TC Series Limited Warranty**

Rice Lake Weighing Systems (RLWS) warrants that all RLWS equipment and systems manufactured and sold by RLWS and properly installed by an authorized RLWS Distributor or Original Equipment Manufacturer (OEM) will operate per written specifications as confirmed by the Distributor/OEM and accepted by RLWS. All systems and components are warranted against defects in materials and workmanship for five years.

RLWS warrants that the equipment sold hereunder will conform to the current written specifications authorized by RLWS. RLWS warrants the equipment against faulty workmanship and defective materials. If any equipment fails to conform to these warranties, RLWS will, at its option, repair or replace such goods returned within the warranty period subject to the following conditions:

- Upon discovery by Buyer of such nonconformity, RLWS will be given prompt written notice with a detailed explanation of the alleged deficiencies.
- Individual electronic components returned to RLWS for warranty purposes must be packaged to prevent electrostatic discharge (ESD) damage in shipment. Packaging requirements are listed in a publication, *Protecting Your Components From Static Damage in Shipment*, available from RLWS Equipment Return Department.
- Examination of such equipment by RLWS confirms that the nonconformity actually exists, and was not caused by accident, misuse, neglect, alteration, improper installation, improper repair or improper testing; RLWS shall be the sole judge of all alleged non-conformities.
- Such equipment has not been modified, altered, or changed by any person other than RLWS or its duly authorized repair agents.
- RLWS will have a reasonable time to repair or replace the defective equipment. Buyer is responsible for shipping charges both ways.
- In no event will RLWS be responsible for travel time or on-location repairs, including assembly or disassembly of equipment, nor will RLWS be liable for the cost of any repairs made by others.

THESE WARRANTIES EXCLUDE ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING WITHOUT LIMITATION WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. NEITHER RLWS NOR DISTRIBUTOR WILL, IN ANY EVENT, BE LIABLE FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES.

RLWS AND BUYER AGREE THAT RLWS' SOLE AND EXCLUSIVE LIABILITY HEREUNDER IS LIMITED TO REPAIR OR REPLACEMENT OF SUCH GOODS. IN ACCEPTING THIS WARRANTY, THE BUYER WAIVES ANY AND ALL OTHER CLAIMS TO WARRANTY.

SHOULD THE SELLER BE OTHER THAN RLWS, THE BUYER AGREES TO LOOK ONLY TO THE SELLER FOR WARRANTY CLAIMS.

NO TERMS, CONDITIONS, UNDERSTANDING, OR AGREEMENTS PURPORTING TO MODIFY THE TERMS OF THIS WARRANTY SHALL HAVE ANY LEGAL EFFECT UNLESS MADE IN WRITING AND SIGNED BY A CORPORATE OFFICER OF RLWS AND THE BUYER.

© 2003 Rice Lake Weighing Systems, Inc. Rice Lake, WI USA. All Rights Reserved.

RICE LAKE WEIGHING SYSTEMS • 230 WEST COLEMAN STREET • RICE LAKE, WISCONSIN 54868 • USA





230 W. Coleman St. • Rice Lake, WI 54868 • USA U.S. 800-472-6703 • Canada/Mexico 800-321-6703 International 715-234-9171

> www.ricelake.com mobile: m.ricelake.com

> > © 2011 Rice Lake Weighing Systems

PN 107243 Rev A

October 17, 2023