





## Uni-5 & Uni-7 and WM-Nano Starter Keyboards



### Uni-5 & Uni-7 Scales

Copy the "Data03" folder to a USB flash drive. In the **File Save / Load** menu load file "Uni-5/7 Starter Keyboard" to the scale. Edit the keyboard as needed.

PLU 0 MAY.10.2013 (FRI) 13:10			TARE lb	0.000
  Check the weight before operation. Enter PLU No. and press [PLU] key.			ZERO WEIGHT lb	0.000
PRINTING	CAT 1	CAT 2	UNIT PRICE \$/lb	0.00
<MANUAL>			TOTAL PRICE \$	0.00
CALC.	CAT 3	CAT 4		
SEARCH	CAT 5	CAT 6		
0				
LABEL BATCH	CAT 7	CAT 8		

Category Page

PLU 1 MAY.10.2013 (FRI) 13:10			NET TARE lb	0.025
  <b>BEEF CHUCK BLADE ROAST</b>			WEIGHT lb	3.220
PRINTING	PACK DATE	SELL BY DATE	UNIT PRICE \$/lb	1.99
<MANUAL>	05.10.13	MAY.13.2013	TOTAL PRICE \$	6.41
CALC.	COUNTRY	LOGO #1 LBL QNTY		
	1	14		
SEARCH	STOP PRINT	PRINT		
1				
RETURN TO PREVIOUS				


PLU 10 MAY.10.2013 (FRI) 13:38			PCS	1
  <b>HAM SANDWICH</b>			@/	1
PRINTING	PACK DATE	SELL BY DATE	UNIT PRICE \$	4.99
<MANUAL>	05.10.13	MAY.12.2013	TOTAL PRICE \$	4.99
CALC.	COUNTRY	LOGO #1 LBL QNTY		
	0	0 3		
SEARCH	STOP PRINT	PRINT		
10				
RETURN TO PREVIOUS				

Function Key Pages


## Uni-5 & Uni-7 and WM-Nano Starter Keyboards


### WM-Nano Wrapper

Copy the "Data02" folder to a USB flash drive. In the **File Save / Load** menu load file "Nano Starter Keyboard" to the wrapper. Edit the keyboard as needed.

PLU 0		MAY.10.2013 (FRI) 12:19		TARE	lb	0.000
 Check the weight before operation. Enter PLU No. and press [PLU] key.				ZERO	WEIGHT lb	0.000
WRAPPER SETTINGS	CAT 1	CAT 2		UNIT PRICE \$/lb		0.00
FILM FEED	CAT 3	CAT 4		TOTAL PRICE \$		0.00
SEARCH	CAT 5	CAT 6				
0	CAT 7	CAT 8				
CALC.						

Category Page




PLU 1		MAY.10.2013 (FRI) 12:19		NET	TARE lb	0.025
 <b>BEEF CHUCK BLADE ROAST</b>				WEIGHT lb	3.220	
FILM FEED	PACK DATE	SELL BY DATE		UNIT PRICE \$/lb		1.99
	MAY. 10. 2013	MAY. 15. 2013		TOTAL PRICE \$		6.41
FILM REMOVE	CLEANING	COUNTRY				
		1				
SEARCH	HEATER ADJUST	SEAL HEATER IS POWER ON(285F)	VOLUME (HIGH)			
1						
WRAPPER RESET	WRAP+ PRINT	TRAY	RETURN TO PREVIOUS			
		8D				




PLU 156		MAY.10.2013 (FRI) 12:19		PCS	1	
 <b>MAINE LOBSTER</b>				@/	1	
FILM FEED	PACK DATE	SELL BY DATE		UNIT PRICE \$		17.99
	MAY. 10. 2013	MAY. 14. 2013		TOTAL PRICE \$		17.99
FILM REMOVE	CLEANING	COUNTRY				
		1				
SEARCH	HEATER ADJUST	SEAL HEATER IS POWER ON(285F)	VOLUME (HIGH)			
156						
WRAPPER RESET	WRAP+ PRINT	TRAY	RETURN TO PREVIOUS			
		8D				




Function Key Pages




## Uni-5 & Uni-7 and WM-Nano Starter Keyboards

### Category Pages


PLU 0					MAY.10.2013 (FRI) 13:10				
   Check the weight before operation. Enter PLU No. and press [PLU] key.					TARE lb				
					0.000				
					ZERO WEIGHT lb				
					0.000				
					UNIT PRICE \$/lb				
					0.00				
					TOTAL PRICE \$				
					0.00				
					CAT 1 (RETURN)				




PLU 0					MAY.10.2013 (FRI) 13:10				
   Check the weight before operation. Enter PLU No. and press [PLU] key.					TARE lb				
					0.000				
					ZERO WEIGHT lb				
					0.000				
					UNIT PRICE \$/lb				
					0.00				
					TOTAL PRICE \$				
					0.00				
					CAT 2 (RETURN)				




PLU 0					MAY.10.2013 (FRI) 13:10				
   Check the weight before operation. Enter PLU No. and press [PLU] key.					TARE lb				
					0.000				
					ZERO WEIGHT lb				
					0.000				
					UNIT PRICE \$/lb				
					0.00				
					TOTAL PRICE \$				
					0.00				
					CAT 3 (RETURN)				




PLU 0					MAY.10.2013 (FRI) 13:10				
   Check the weight before operation. Enter PLU No. and press [PLU] key.					TARE lb				
					0.000				
					ZERO WEIGHT lb				
					0.000				
					UNIT PRICE \$/lb				
					0.00				
					TOTAL PRICE \$				
					0.00				
					CAT 4 (RETURN)				

## Uni-5 & Uni-7 and WM-Nano Starter Keyboards


PLU 0					MAY.10.2013 (FRI) 13:10					TARE lb	
   Check the weight before operation. Enter PLU No. and press [PLU] key.					0.000		ZERO		WEIGHT lb		
					0.000						
					UNIT PRICE \$/lb		0.00				
					TOTAL PRICE \$		0.00				
					CAT 5		(RETURN)				

PLU 0					MAY.10.2013 (FRI) 13:10					TARE lb	
   Check the weight before operation. Enter PLU No. and press [PLU] key.					0.000		ZERO		WEIGHT lb		
					0.000						
					UNIT PRICE \$/lb		0.00				
					TOTAL PRICE \$		0.00				
					CAT 6		(RETURN)				

PLU 0					MAY.10.2013 (FRI) 13:10					TARE lb	
   Check the weight before operation. Enter PLU No. and press [PLU] key.					0.000		ZERO		WEIGHT lb		
					0.000						
					UNIT PRICE \$/lb		0.00				
					TOTAL PRICE \$		0.00				
					CAT 7		(RETURN)				

PLU 0					MAY.10.2013 (FRI) 13:10					TARE lb	
   Check the weight before operation. Enter PLU No. and press [PLU] key.					0.000		ZERO		WEIGHT lb		
					0.000						
					UNIT PRICE \$/lb		0.00				
					TOTAL PRICE \$		0.00				
					CAT 8		(RETURN)				

## Uni-5 & Uni-7 and WM-Nano Starter Keyboards



Membrane Preset Keyboard