


BENCH SCALES
CW-90B



Part Number/Price

Ref #	Part #	Description	Price
	200153	Technical manual	Consult
1	107144	Cover, 10 × 10 in	Consult
1	105457	Cover, 12 × 12 in	Consult
2	107140	Spider Plate, 10 × 10 in	Consult
2	105450	Spider Plate, 12 × 12 in	Consult
3	105555	Coupling nut 1/4-20NC x 0.48, hex SS	Consult
4	106462	Screw, cap 1/4-20NC x 1-1/2 hex SS	Consult
5	32860	Load cell, RL1040-7kg (5 lb model)	Consult
5	32861	Load cell, RL1040-10kg (10 lb model)	Consult
5	32864	Load cell, RL1040-30kg (25 lb models)	Consult
5	188679	Load cell, RL42018A-50kg (50 lb model)	Consult
5	188681	Load cell, RL42018A-100kg (100 lb model)	Consult
6	107142	Base plate, 10 × 10 in	Consult
6	105452	Base plate, 12 × 12 in	Consult
7	45329	Screw, mach 8-32NC x 3/16 SS	Consult
8	52342	Label, bench scale	Consult
9	107476	Bench scale foot	Consult
10	52383	Load cell shim	Consult
11	15148	Washer, locking	Consult
12	14963	Overload screw, 1/4-20NC x 3/4	Consult
13	15410	Spirit level bubble, plastic	Consult
14	21948	Screw, load cell	Consult
15	35082	Top shim, load cell	Consult
16	163794	Cap screw 1/4-20NF x 1/2, flat SS (5 lb to 25 lb models)	Consult
16	14960	Cap screw 1/4-20NC x 1/2, hex SS (50 lb to 100 lb models)	Consult

(See diagram XXXXX)

CW-90B

Cable length: 34 in

107756	Load cell, RL1040 - 7 kg (5 lb scale)	Consult
107757	Load cell, RL1040 - 10 kg (10 lb scale)	Consult
107758	Load cell, RL1040 - 30 kg (25 lb scale)	Consult
107759	Load cell, RL1040 - 50 kg (50 lb scale)	Consult
107760	Load cell, RL1040 - 100 kg (100 lb scale)	Consult

