

FOR A SUCCESSFUL INSTALLATION

We would like you and your customer to get years of productivity from your weighing system(s). Please review the following prior to your system's installation and/or calibration.

REQUIRED EQUIPMENT AND DOCUMENTATION

These items are required in preparing for installation, configuration, simulated calibration, pre-calibration, or final calibration for MSI scales and systems.

- Laptop (with MSI Configuration Program downloaded)
- Product specific serial cables
- Tripplite USB to serial converter cable
- Manual(s)

Available as digital or hard copy for your technician to use during installation, set up, calibration or troubleshooting. Supplied on CD with order or at www.ricelake.com/manuals.

- Load cell simulator (optional)
- System schematic (optional) (supplied by request at time of order)
- Test weights for calibration and weight verification (required for integrated systems)

Measurement Systems International



BEST PRACTICES FOR A SUCCESSFUL AND TIMELY INSTALLATION

- Power on the electronics before installation to ensure basic functionality.
- Review the manual(s) prior to the system installation to familiarize yourself with the set up/calibration.
- Perform a practice configuration of your weighing system, before attempting it on-site.
- Was your system factory calibrated?
 Perform a simulated calibration prior to installation to test the calibration of your system.
- Leave a serial cable at the customer site for troubleshooting at a later date.

TROUBLESHOOTING TIPS FOR PROBLEMS DURING INSTALLATION

- Consult system optional schematic for wiring and check all connections
- Ensure proper grounding of all components
- If experiencing communication errors:
 - Evaluate RF distance and antenna locations
 - Locate sources of radio transmissions
 I.E. crane remotes, Wifi/Bluetooth modems, competing RF weighing systems
- Perform an RF site survey (rental available)
- Request on-site support from a factory representative
- Document your system by recording all networks, IDs, serial numbers, and/or print strings associated with your system to assist with MSI over the phone support



800-472-6703 • prodinfo@ricelake.com **www.ricelake.com**

© 2018 Rice Lake Weighing Systems PN 187004 11/18 Specifications subject to change without notice.