

Uni-8

Bench, Printer




Part Number/Price

Ref #	Part #	Description	Synonym	Qty	Price
1	223513	TFT, screen, 10 inch, operator display	400-000-7008-00	1	Consult
2	223514	Case front, operator display	400-000-7009-00	1	Consult
3	223515	Bracket, 10 inch TFT, operator display, zinc plated	400-000-7010-00	1	Consult
4	223516	Damping hinge, assy, operator display	400-000-7011-00	1	Consult
5	223517	Case, rear, operator display	400-000-7012-00	1	Consult
6	223518	Harness C2, operator display, 10 inch TFT to CPU USB3	400-000-7013-00	1	Consult
7	223519	LVDS board, junction, operator display	400-000-7014-00	1	Consult
8	Consult	Bracket-MB	400-000-7015-00	1	Consult
9	Consult	Connector	400-000-7016-00	1	Consult
10	Consult	Wi-Fi sticker	400-000-7017-00	1	Consult
11	Consult	Name plate, multi-range	400-000-7018-00	1	Consult
11	Consult	Name plate, single-range	400-000-7019-00	1	Consult
12	223520	Harness C4 (power switch to power switching board L N)	400-000-7020-00	1	Consult
13	223521	Switch, rocker, power	400-000-7021-00	1	Consult
14	223522	PWB PS-105, register board	400-000-7022-00	1	Consult
15	223523	PWB PS-063, span switch board	400-000-7023-00	1	Consult
16	223524	Harness C2, PS-105 CN5 to PS-096C XJ5	400-000-7024-00	1	Consult
17	Consult	Strain relief bushing	400-000-7025-00	1	Consult
18	223525	Power cord, hard-wired, three prong	400-000-7026-00	1	Consult
19	223526	Harness C2, P-097 CN3 to CPU 12V in	400-000-7027-00	1	Consult
20	223527	Harness, operator display, LVDS board CN1 to CPU LVDS1	400-000-7028-00	1	Consult
21	Consult	Harness audio out	400-000-7029-00	1	Consult
22	223528	PWB PS-100, CPU board	400-000-7030-00	1	Consult
23	223529	Harness, PS-098-CN3 to CPU-LVDS2	400-000-7031-00	1	Consult
24	Consult	Speaker	400-000-7032-00	1	Consult
25	Consult	Bracket-op-display	400-000-7033-00	1	Consult
26	Consult	Bracket-op	400-000-7034-00	1	Consult
27	223530	Faceplate, case, front, hinge, plastic	400-000-7035-00	1	Consult
28	223531	Cover, case, front, printer, plastic	400-000-7036-00	1	Consult
29	Consult	Bracket	400-000-7037-00	1	Consult
30	130813	Foot leveling, M6-1.0x32 mm	000-089-5083-06	4	Consult
—	92169	Nut, SST, M6-1.0	—	8	Consult
31	223533	Ferrite core	400-000-7039-00	1	Consult
32	223534	PWB PS-067, AD board	400-000-7040-00	1	Consult
33	223535	Harness C2, PS-096C XJ2 to CPU USB4	400-000-7041-00	1	Consult
34	223536	PWB PS-096C, printer board	400-000-7042-00	1	Consult
35	223537	Harness S2, PS-097 CN7 to PS-096C XJ3	400-000-7043-00	1	Consult
36	223538	Ferrite core	400-000-7044-00	2	Consult
37	223539	Sticker, loading instructions, printer	400-000-7045-00	1	Consult
38	Consult	Bracket	400-000-7046-00	1	Consult
39	223540	Cover, case, right, printer door	400-000-7047-00	1	Consult
40	223541	Hinge, plastic	400-000-7048-00	2	Consult
41	Consult	Base	400-000-7049-00	1	Consult
42	223542	Harness, (PS-098 CN1 to LVDS junction board, customer display)	400-000-7050-00	1	Consult
43	223544	PWB PS-098, connector	400-000-7051-00	1	Consult
44	223545	PWB PS-097, power board	400-000-7052-00	1	Consult
45	223546	Harness S3, PS-097 CN1 to power switching board -V +V	400-000-7053-00	1	Consult
46	Consult	Pole base cover	400-000-7054-00	1	Consult
47	Consult	Pole base	400-000-7055-00	1	Consult
48	223547	Display base, aluminum	400-000-7056-00	1	Consult
49	Consult	Bracket lock	400-000-7057-00	1	Consult
50	Consult	Ferrite core	400-000-7058-00	1	Consult
51	223548	Case, rear, customer display	400-000-7059-00	1	Consult
52	223549	Damping hinge, assy, customer display	400-000-7060-00	1	Consult
53	223550	LVDS board, junction, customer display	400-000-7061-00	1	Consult
54	223551	Bracket, 7-inch TFT, customer display, zinc plated	400-000-7062-00	1	Consult
55	223552	TFT, screen, 7-inch, customer display	400-000-7063-00	1	Consult
56	223553	Case, front, customer display	400-000-7064-00	1	Consult

Uni-8

Bench, Printer



Printing Scales


Uni-8

Bench, Printer



Printing Scales

Ref #	Part #	Description	Synonym	Qty	Price
57	223554	Sheet, customer display	400-000-7065-00	1	Consult
58	223555	Power switching board	400-000-7066-00	1	Consult
59	Consult	Harness S2 GND	400-000-7067-00	1	Consult
60	Consult	Base	400-000-7068-00	1	Consult
61	223557	Load cell, 30 lb, 15 kg	400-000-7069-00	1	Consult
62	Consult	Plate support, weigh spider	400-000-7070-00	1	Consult
63	223558	Rubber support, weigh spider	400-000-7071-00	4	Consult
64	223604	Magnet, catch, printer door	400-000-7072-00	1	Consult
65	223559	Case, main body	400-000-7073-00	1	Consult
66	Consult	Lens	400-000-7074-00	1	Consult
67	223560	Weigh platter	400-000-6840-00	1	Consult
68	223561	Guide, weigh platter	400-000-6914-00	1	Consult
69	Consult	Bracket	400-000-7077-00	1	Consult
70	Consult	Screw	400-000-7078-00	1	Consult
71	223562	Tear plate	400-000-7079-00	1	Consult
72	223563	Printhead, thermal	400-000-7080-00	1	Consult
73	223564	Harness S2, printhead, thermal to PS-096C XJ9	400-000-7081-00	1	Consult
74	223565	Spring coil 2	400-000-7082-00	2	Consult
75	Consult	Bracket head	400-000-7083-00	1	Consult
76	Consult	Frame head	400-000-7084-00	1	Consult
77	Consult	Shaft 1	400-000-7085-00	1	Consult
78	Consult	Bracket	400-000-7086-00	1	Consult
79	Consult	Axis 01	400-000-7087-00	1	Consult
80	Consult	Axis 002	400-000-7088-00	1	Consult
81	Consult	Support-NL	400-000-7089-00	1	Consult
82	Consult	Bush left pom	400-000-7090-00	2	Consult
83	Consult	Bush	400-000-7091-00	1	Consult
84	223566	Shaft, roller, plastic	400-000-7092-00	1	Consult
85	Consult	Label guide	400-000-7093-00	1	Consult
86	Consult	Cover-NL	400-000-7094-00	1	Consult
87	Consult	Bracket of fixed	400-000-7095-00	1	Consult
88	223567	Bracket, take spool	400-000-7096-00	1	Consult
89	223568	Spring	400-000-7097-00	1	Consult
90	223569	Shaft	400-000-7098-00	1	Consult
91	223570	Axle bushings, textured roller	400-000-7099-00	16	Consult
92	223572	Support, housing, gap sensor, nylon	400-000-7100-00	1	Consult
93	223574	Holder, label supply reel, mount	000-089-6667-04	1	Consult
94	66376	Lever guide, lock, label supply reel	000-089-2858-04	1	Consult
95	66378	Holder, guide, label supply reel	000-089-2830-01	1	Consult
96	Consult	Frame	400-000-7101-00	1	Consult
97	Consult	Level unit	400-000-7102-00	1	Consult
98	223576	Gear, stepped, dual teeth	400-000-7103-00	1	Consult
99	223605	Bracket, cover, label gap	400-000-7104-00	2	Consult
100	Consult	Bush	400-000-7105-00	1	Consult
101	223577	Sensor, label gap, assy, send and receive	400-000-7336-00	1	Consult
102	Consult	Bracket motor	400-000-7107-00	1	Consult
103	223578	Motor stepping	400-000-7108-00	1	Consult
104	223580	Axis rewind	400-000-7109-00	1	Consult
105	223581	Timing belt	400-000-7110-00	1	Consult
106	223583	Gear rewind	400-000-7111-00	1	Consult
107	223584	Torque limit	400-000-7112-00	1	Consult
108	Consult	Bracket 01	400-000-7113-00	1	Consult
109	Consult	Bush	400-000-7114-00	1	Consult
110	223585	Gear, driver	400-000-7115-00	1	Consult
111	223586	Cover, gear, driver	400-000-7116-00	1	Consult
112	223587	Platen roller, rubber, printhead	400-000-7117-00	1	Consult
113	223588	Harness, peel sensor, to PS-096C XJ11	400-000-7118-00	1	Consult
114	223589	Peel sensor	400-000-7119-00	1	Consult
115	223590	Bracket, peel sensor	400-000-7120-00	1	Consult
116	223591	Bracket, printhead, open close	400-000-7121-00	1	Consult
117	223592	Spring coil 1	400-000-7122-00	2	Consult
118	Consult	Axis hold	400-000-7123-00	1	Consult
119	223593	Jumper cap	400-000-7337-00	2	Consult




Uni-8

Pole, Printer



Part Number/Price

Ref #	Part #	Description	Synonym	Qty	Price
1	223513	TFT, screen, 10 inch, operator display	400-000-7008-00	1	Consult
2	223514	Case front, operator display	400-000-7009-00	1	Consult
3	223515	Bracket, 10 inch TFT, operator display, zinc plated	400-000-7010-00	1	Consult
4	223516	Damping hinge, assy, operator display	400-000-7011-00	1	Consult
5	223517	Case, rear, operator display	400-000-7012-00	1	Consult
6	223518	Harness C2, operator display, 10 inch TFT to CPU USB3	400-000-7013-00	1	Consult
7	223519	LVDS board, junction, operator display	400-000-7014-00	1	Consult
8	Consult	Bracket-MB	400-000-7015-00	1	Consult
9	Consult	Connector	400-000-7016-00	1	Consult
10	Consult	Wi-Fi sticker	400-000-7017-00	1	Consult
11	Consult	Name plate, multi-range	400-000-7018-00	1	Consult
11	Consult	Name plate, single-range	400-000-7019-00	1	Consult
12	223520	Harness C4 (power switch to power switching board L N)	400-000-7020-00	1	Consult
13	223521	Switch, rocker, power	400-000-7021-00	1	Consult
14	223522	PWB PS-105, register board	400-000-7022-00	1	Consult
15	223523	PWB PS-063, span switch board	400-000-7023-00	1	Consult
16	223524	Harness C2, PS-105 CN5 to PS-096C XJ5	400-000-7024-00	1	Consult
17	Consult	Strain relief bushing	400-000-7025-00	1	Consult
18	223525	Power cord, hard-wired, three prong	400-000-7026-00	1	Consult
19	223526	Harness C2, P-097 CN3 to CPU 12V in	400-000-7027-00	1	Consult
20	223527	Harness, operator display, LVDS board CN1 to CPU LVDS1	400-000-7028-00	1	Consult
21	Consult	Harness audio out	400-000-7029-00	1	Consult
22	223528	PWB PS-100, CPU board	400-000-7030-00	1	Consult
23	223529	Harness, PS-098-CN3 to CPU-LVDS2	400-000-7031-00	1	Consult
24	Consult	Speaker	400-000-7032-00	1	Consult
25	Consult	Bracket-op-display	400-000-7033-00	1	Consult
26	Consult	Bracket-op	400-000-7034-00	1	Consult
27	223530	Faceplate, case, front, hinge, plastic	400-000-7035-00	1	Consult
28	223531	Cover, case, front, printer, plastic	400-000-7036-00	1	Consult
29	Consult	Bracket	400-000-7037-00	1	Consult
30	130813	Foot leveling, M6-1.0x32 mm	000-089-5083-06	4	Consult
31	223533	Ferrite core	400-000-7039-00	1	Consult
32	223534	PWB PS-067, AD board	400-000-7040-00	1	Consult
33	223535	Harness C2, PS-096C XJ2 to CPU USB4	400-000-7041-00	1	Consult
34	223536	PWB PS-096C, printer board	400-000-7042-00	1	Consult
35	223537	Harness S2, PS-097 CN7 to PS-096C XJ3	400-000-7043-00	1	Consult
36	223538	Ferrite core	400-000-7044-00	2	Consult
37	223539	Sticker, loading instructions, printer	400-000-7045-00	1	Consult
38	Consult	Bracket	400-000-7046-00	1	Consult
39	223540	Cover, case, right, printer door	400-000-7047-00	1	Consult
40	223541	Hinge, plastic	400-000-7048-00	2	Consult
41	Consult	Base	400-000-7049-00	1	Consult
42	223651	Harness LVDS	400-000-7031-00	1	Consult
43	223544	PWB PS-098, connector	400-000-7051-00	1	Consult
44	223545	PWB PS-097, power board	400-000-7052-00	1	Consult
45	223546	Harness S3, PS-097 CN1 to power switching board -V +V	400-000-7053-00	1	Consult
46	Consult	Bracket	400-000-7129-00	1	Consult
47	Consult	Pole base	400-000-7131-00	1	Consult
48	223652	Case, lower, base, pole	400-000-7132-00	1	Consult
49	223654	Pole	400-000-7133-00	1	Consult
50	223655	Case, upper, hinge, pole	400-000-7134-00	1	Consult
51	223548	Case, rear, customer display	400-000-7059-00	1	Consult
52	223549	Damping hinge, assy, customer display	400-000-7060-00	1	Consult
53	223550	LVDS board, junction, customer display	400-000-7061-00	1	Consult
54	223551	Bracket, 7-inch TFT, customer display, zinc plated	400-000-7062-00	1	Consult
55	223552	TFT, screen, 7-inch, customer display	400-000-7063-00	1	Consult
56	223553	Case, front, customer display	400-000-7064-00	1	Consult
57	223554	Sheet, customer display	400-000-7065-00	1	Consult
58	223555	Power switching board	400-000-7066-00	1	Consult




Uni-8

Pole, Printer



Ref #	Part #	Description	Synonym	Qty	Price
59	Consult	Harness S2 GND	400-000-7067-00	1	Consult
60	Consult	Base	400-000-7068-00	1	Consult
61	223557	Load cell, 30 lb, 15 kg	400-000-7069-00	1	Consult
62	Consult	Plate support, weigh spider	400-000-7070-00	1	Consult
63	223558	Rubber support, weigh spider	400-000-7071-00	4	Consult
64	223604	Magnet, catch, printer door	400-000-7072-00	1	Consult
65	223559	Case, main body	400-000-7073-00	1	Consult
66	Consult	Lens	400-000-7074-00	1	Consult
67	223560	Weigh platter	400-000-6840-00	1	Consult
68	223561	Guide, weigh platter	400-000-6914-00	1	Consult
69	Consult	Bracket	400-000-7077-00	1	Consult
70	Consult	Screw	400-000-7078-00	1	Consult
71	223562	Tear plate	400-000-7079-00	1	Consult
72	223563	Printhead, thermal	400-000-7080-00	1	Consult
73	223564	Harness S2, printhead, thermal to PS-096C XJ9	400-000-7081-00	1	Consult
74	223565	Spring coil 2	400-000-7082-00	2	Consult
75	Consult	Bracket head	400-000-7083-00	1	Consult
76	Consult	Frame head	400-000-7084-00	1	Consult
77	Consult	Shaft 1	400-000-7085-00	1	Consult
78	Consult	Bracket	400-000-7086-00	1	Consult
79	Consult	Axis 01	400-000-7087-00	1	Consult
80	Consult	Axis 002	400-000-7088-00	1	Consult
81	Consult	Support-NL	400-000-7089-00	1	Consult
82	Consult	Bush left pom	400-000-7090-00	2	Consult
83	Consult	Bush	400-000-7091-00	1	Consult
84	223566	Shaft, roller, plastic	400-000-7092-00	1	Consult
85	Consult	Label guide	400-000-7093-00	1	Consult
86	Consult	Cover-NL	400-000-7094-00	1	Consult
87	Consult	Bracket of fixed	400-000-7095-00	1	Consult
88	223567	Bracket, take spool	400-000-7096-00	1	Consult
89	223568	Spring	400-000-7097-00	1	Consult
90	223569	Shaft	400-000-7098-00	1	Consult
91	223570	Axle bushings, textured roller	400-000-7099-00	16	Consult
92	223572	Support, housing, gap sensor, nylon	400-000-7100-00	1	Consult
93	223574	Holder, label supply reel, mount	000-089-6667-04	1	Consult
94	66376	Lever guide, lock, label supply reel	000-089-2858-04	1	Consult
95	66378	Holder, guide, label supply reel	000-089-2830-01	1	Consult
96	Consult	Frame	400-000-7101-00	1	Consult
97	Consult	Level unit	400-000-7102-00	1	Consult
98	223576	Gear, stepped, dual teeth	400-000-7103-00	1	Consult
99	223605	Bracket, cover, label gap	400-000-7104-00	2	Consult
100	Consult	Bush	400-000-7105-00	1	Consult
101	223577	Sensor, label gap, assy, send and receive	400-000-7336-00	1	Consult
102	Consult	Bracket motor	400-000-7107-00	1	Consult
103	223578	Motor stepping	400-000-7108-00	1	Consult
104	223580	Axis rewind	400-000-7109-00	1	Consult
105	223581	Timing belt	400-000-7110-00	1	Consult
106	223583	Gear rewind	400-000-7111-00	1	Consult
107	223584	Torque limit	400-000-7112-00	1	Consult
108	Consult	Bracket 01	400-000-7113-00	1	Consult
109	Consult	Bush	400-000-7114-00	1	Consult
110	223585	Gear, driver	400-000-7115-00	1	Consult
111	223586	Cover, gear, driver	400-000-7116-00	1	Consult
112	223587	Platen roller, rubber, printhead	400-000-7117-00	1	Consult
113	223588	Harness, peel sensor, to PS-096C XJ11	400-000-7118-00	1	Consult
114	223589	Peel sensor	400-000-7119-00	1	Consult
115	223590	Bracket, peel sensor	400-000-7120-00	1	Consult
116	223591	Bracket, printhead, open close	400-000-7121-00	1	Consult
117	223592	Spring coil 1	400-000-7122-00	2	Consult
118	Consult	Axis hold	400-000-7123-00	1	Consult
119	Consult	Bracket lock	400-000-7057-00	1	Consult
120	Consult	Ferrite core	400-000-7058-00	1	Consult
121	223593	Jumper cap	400-000-7337-00	2	Consult




Printing Scales

Uni-8

Electric Unit Wiring Diagram



Printing Scales



Printing Scales